Bruhath Bangalore Mahanagar Palike
Rajarajeshwari Nagar Zone.

WORK COMPLETION REPORT

1	Name of the work	Repair and replacing of Damaged LTUG cables at JP park JP Park Play ground in ward No 17
2	Sanctioned Estimate No. & Date	EE/ELE/AS/40/17-18, Dtd:10/01/18
3	Head Of Account	P-0298-M & R to Electrical Installations in Parks, Gardens, play Grounds and Burial Grounds
4	Work Order No & Date	EE/ELE/RRN/WO/15/18-19, Dtd: ~~08-02-2018~~ 02/08/2018
5	Name Of the Contractor	**M/s Prema Electrical Enterprises**
6	Amount of Estimate Rs.	Rs. 100000.00
7	Amoun of Expenditure Rs.	98814.00.00
	Excess Rs.	-
	Saving Rs.	1186.00
8	Date of Commencement of Work	~~08-02-2018~~ 02/08/2018
9	Date Of Completion of Work	29/09/18
10	Measurement Book No & Page No:	2219/18-19 221850-221853
11	Name of the Subordinate incharge of Work.	Ramesh HV. AEE(Ele)
12	Name of Inspecting officer	Ramanjaneya S.C. EE(Ele)
13	Other details if Any	

This is to certifiy that the work of **Repair and replacing of Damaged LTUG cables at JP park JP Park Play ground in ward No 17** Has been Executed and completed in all respect satisfactorily as per the sanctioned estimate and plan.

Junior .Engineer(Ele)
R.R Nagar , BBMP.

Asst .Exe.Engineer(Ele)
Bruhath Bangalore Mahanagara Palike
Rajarajeshwari Nagar Zone.

Executive Engineer(Ele)
.Bruhath Bangalore Mahanagara Palike
Rajarajeshwari Nagar Zone.